


Department of Environmental Protection		GENERAL INSPECTION REPORT		Bureau of Land Recycling and Waste Management	
Type of Inspection	WM Identification Number	Entry Time/Date	Inspection ID		
Complaint response	Site ID: 865337	3/14/2024	3728358		
Facility/Incident Name and Location			Municipality		
Kingdom Provisions			Plumstead		
5960 Durham Road Pipersville PA 18947			County Bucks		
Name, Address of Responsible Official		Title			
Ephriam Stoltzfus –		Owner			
Kerry Rush – Owner Brent Pressley - Manager Amber Pressley - Manager		Telephone	Interviewed		
		215-767-8943	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		

On March 14, 2024, I, Jonathan Bower, Solid Waste Supervisor, received a complaint about the land application of food processing residual (FPR) material from the Kingdom Provisions (KP) butchering operations. On this day the weather was dry and it had not rained for a several days.

Observations were first made from the property located at 6030 Durham Road, the site where a release of FPR material was observed on March 5, 2024. Small area of pooling water or puddles were present, but no staining or red color was observed. Along the fence line separating the 6030 property from the KP property, on the KP side, an earthen berm is present. Adjacent to this berm some pooling water was occurring. That water did not appear, visually, to contain FPR material.

Next a complaint investigation was conducted at KP. Amber Presley, Manager, was present and available to discuss the land application of FPR. Previous to this inspection, KP had been working with the Department to provide information requested in response to the March 5, 2024, incident response. At the time of the inspection KP provided a copy of the manure management plan, as well as land application logs and disposal documentation for liquid waste. From the information provided it appears that KP has land applied 750 gallons on 4 occasions beginning March 1, 2024, to 3 separate 1/8-acre fields. Additionally, KP has had 36,000 gallons or 9 tanker truck loads of this material removed by a septic hauler Brad S. Nicolas. A tanker was present and

Inspector Name	Inspector Signature	Headquarters	Date
Jonathan Bower		SERO 2 East Main Street	3/14/2024
		Norristown, PA 19401	Telephone 484-250-5753
Person Interviewed Name	Signature of Person Interviewed	Title	Telephone
Amber Pressley	Delivered electronically	Manager	215-767-8943

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either violations noted herein, or other violations identified as a result of review of laboratory analyses or Department records.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
-------------------------------------------	------------------------------	--------------------------------------------------

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks

being loaded at the time of the inspection. KP should keep all land application logs and disposal documentation on site, in a way that they can be made available during inspections and complaint investigations.

A site walk was conducted. From the road in the center of the site two of the fields had been further tilled. Standing water and/or FPR material was not observed during this site walk. The fields were too rough to easily walk across, so the property line was discussed from this location. It was explained that while an earthen berm was observed, it could be improved by keeping it off the fence line, shaped or graded to not allow standing water and vegetation or supporting root structure should be provided. It was also noted the there was a pool of water currently in this area that should be regraded.

Additionally, the water course noted in the last inspection, that runs through the site between fields, has been identified as an unnamed tributary to Cabin Run. The land application of FPR material should not be allowed to enter or otherwise affect this watercourse or waterways of the Commonwealth.

No violations cited.

Inspector Name Jonathan Bower	Inspector Signature <i>JONATHAN BOWER</i>	Date 3/14/2024
-----------------------------------------	----------------------------------------------	--------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
-------------------------------------------	------------------------------	--------------------------------------------------

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks



Image 1: Image taken at 6030 Durham Rd. displaying pooling storm water.
Taken by Jonathan Bower on 3/14/2024

Inspector Name Jonathan Bower	Inspector Signature <i>JONATHAN BOWER</i>	Date 3/14/2024
-----------------------------------------	----------------------------------------------	--------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
-------------------------------------------	------------------------------	--------------------------------------------------

Facility/Incident Name and Location Kingdom Provisions 5960 Durham Road Pipersville PA 18947	Municipality Plumstead County Bucks
---------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------



Image 2: Image taken at 6030 Durham Rd. at the fence line where a berm is present and storm water is pooling.

Taken by Jonathan Bower on 3/14/2024

Inspector Name Jonathan Bower	Inspector Signature <i>JONATHAN BOWER</i>	Date 3/14/2024
------------------------------------------------	-----------------------------------------------------	---------------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
-------------------------------------------	------------------------------	--------------------------------------------------

Facility/Incident Name and Location Kingdom Provisions 5960 Durham Road Pipersville PA 18947	Municipality Plumstead County Bucks
---------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------



Image 3: Image taken at Kingdom Provision displaying the pumping and removal of liquid waste.
Taken by Jonathan Bower on 3/14/2024

Inspector Name Jonathan Bower	Inspector Signature <i>JONATHAN BOWER</i>	Date 3/14/2024
------------------------------------------------	-----------------------------------------------------	---------------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
-------------------------------------------	------------------------------	--------------------------------------------------

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks



Image 4: Image taken at Kingdom Provisions of the field where land application has occurred.
Taken by Jonathan Bower on 3/14/2024

Inspector Name Jonathan Bower	Inspector Signature <i>JONATHAN BOWER</i>	Date 3/14/2024
-----------------------------------------	----------------------------------------------	--------------------------