

Department of Environmental Protection		GENERAL INSPECTION REPORT		Bureau of Land Recycling and Waste Management	
Type of Inspection	WM Identification Number	Entry Time/Date	Inspection ID		
Follow up inspection	Site ID: 865337	6/20/2024	3782574		
Facility/Incident Name and Location			Municipality		
Kingdom Provisions			Plumstead		
5960 Durham Road Pipersville PA 18947			County Bucks		
Name, Address of Responsible Official		Title			
Samir Hammed		Manager			
		Telephone	Interviewed		
		215-767-8943	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		

On June 20, 2024, I, Bedhr Salam Majeed, Environmental Trainee, conducted an inspection at Kingdom Provisions (KP). Weather during this inspection was 80°F partly cloudy, humidity 70% with winds 5mph SW:11mph gusts. This inspection was also conducted in response to complaint ID 381342.

Prior to arriving on site, the surrounding area was surveyed for odors. This was done by driving from East and West on Durham Road. No odors were detected on Durham prior to arrival. At the front of the building, I met with Samir Hammed (Operations Manager) and Brent Gouldey (Site Manager) who allowed me access to the site.

At the rear of the building there are 2 chutes, equipped with small conveyors where food processing residuals (FPR) from the butchering process exit the building. At the time of this inspection no containers designated for offsite reuse of FPR was observed. Two top load waste containers were present that are approximately 5 to 7 yards in capacity.

Inspector Name	Inspector Signature	Headquarters	Date
Bedhr Salam Majeed	<i>Bedhr Salam Majeed</i>	SERO 2 East Main Street	6/21/2024
		Norristown, PA 19401	Telephone 484-250-5766
Person Interviewed Name	Signature of Person Interviewed	Title	Telephone
Samir Hammed	Delivered electronically	Manager	215-767-8943

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either violations noted herein, or other violations identified as a result of review of laboratory analyses or Department records.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
Facility/Incident Name and Location		Municipality
Kingdom Provisions		Plumstead
5960 Durham Road Pipersville PA 18947		County Bucks

The site walk continued back to the composting area. FPR liquids have recently been applied on a field SE of the building adjacent to the roadway leading to the windrow piles. A very slight manure odor was detected walking past this field. The roadway that leads to the windrowed compost piles was free of animal remains and no pooling of FPR material was observed. A slight composting odor was detected approximately twenty feet from the compost windrows. The composting odor would decrease to no odor as you walked South to the back of the composting area. The composting area consisted of two (2) windrow compost piles approximately 50 feet in length, 8 feet in width and 4 feet in height. Pile #1 appears to have been managed, by turning material and providing cover in a way that this pile was sufficiently producing a compost material. Pile #2 also showed proper turning and cover sufficiently producing a compost material. No pooling of blood or FPR material were present around these windrow piles. No vectors were observed including turkey vultures were not present in air, near the compost piles or on the KP property, at the time of the inspection. Brent stated previously degraded compost was getting mixed into both piles as this material was enhancing KP compost efforts. DEP asked if additional lifts of woodchips could be applied to both windrow piles. Samir and Brent both agreed to do so. A delivery of wood chips is expected on site 6/20/2024.

The walk continued through the field West of the composting area. No FPR material or composting material were found in this field, on the property line or deposited on other areas of the property. Odors like the odors observed in the compost area were not detected in this field nor at the North or South side of the building. The odors observed in the compost area were not observed off site at the time of this inspection.

Upon leaving the site weather conditions were 82°F, 70% humidity, Partly Cloudy with winds 5mph SW: 11mph gusts.

Kingdom Provisions was asked about the development of a plan that addresses all aspects of the management of FPR material. Mr. Hammed stated the plan is currently being developed and would submit a plan in July of 2024 that would address the best management practices for the management of FPR as compost as well as a land application system (LAS). Comments have been provided by the Department to KP addressing the manure management plan previously submitted, addressing the LAS of FPR. As of the date of this report the Department has not received additional information about BMP from KP.

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
---	--	--------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
---	------------------------------	--

Facility/Incident Name and Location Kingdom Provisions 5960 Durham Road Pipersville PA 18947	Municipality Plumstead County Bucks
---	--



6

Image 1: Image taken behind animal processing building
Taken by Bedhr Salam Majeed on 6/20/2024

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
--	---	---------------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
---	------------------------------	--

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks



Image 2: Image of the roadway leading to the windrow composting piles.
Taken by Bedhr Salam Majeed on 6/20/2024.

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
---	--	--------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
---	------------------------------	--

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks



Image 3: Image of the compost windrow piles.
Taken by Bedhr Salam Majeed on 6/20/2024.

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
---	--	--------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
---	------------------------------	--

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks



Image 4: Image of the compost windrow piles.
Taken by Bedhr Salam Majeed on 6/20/2024.

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
---	--	--------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
---	------------------------------	--

Facility/Incident Name and Location Kingdom Provisions 5960 Durham Road Pipersville PA 18947	Municipality Plumstead County Bucks
---	--



Image 5: Image of the compost windrow piles.
 Taken by Bedhr Salam Majeed on 6/20/2024

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
--	---	---------------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
---	------------------------------	--

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks



Image 6: Image of the compost windrow piles.
Taken by Bedhr Salam Majeed on 6/20/2024

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
---	--	--------------------------

Department of Environmental Protection	GENERAL INSPECTION REPORT	Bureau of Land Recycling and Waste Management
---	------------------------------	--

Facility/Incident Name and Location	Municipality
Kingdom Provisions	Plumstead
5960 Durham Road Pipersville PA 18947	County
	Bucks



Image 6: Image of the field adjacent to windrow piles looking North.
Taken by Bedhr Salam Majeed on 6/20/2024

Inspector Name Bedhr Salam Majeed	Inspector Signature <i>Bedhr Salam Majeed</i>	Date 6/21/2024
---	--	--------------------------