

Date(s) of Inspection: <b>3/27/24</b>	TV <input type="checkbox"/> SM <input type="checkbox"/> NM <input type="checkbox"/>	PA <input type="checkbox"/> GP <input type="checkbox"/> MEGA <input type="checkbox"/>	Permit #(s): _____	Expiration Date: _____	Case #: _____	PF ID #: <b>868000</b>
Company Name: <b>Kingdom Provisions</b>			Municipality: <b>Plumstead Twp</b>		County: <b>BUCKS</b>	
Plant Name: <b>same as above</b>			Physical Location: <b>same as below</b>		Federal ID — Plant Code #:	
Responsible Official: <b>Ephraim Soltzfus</b>				Mailing Address: <b>5960 Durham Rd</b>		
Title: <b>owner</b>				<b>Pipersville, PA 18947</b>		
Phone #(s): <b>267-914-7430</b>						

**Mark (X) All Inspection Types That Apply To This Inspection:**

<input type="checkbox"/> Full Compliance Evaluation (FCE)	<input type="checkbox"/> Plan Approval Inspection	<input type="checkbox"/> File Review (FR)
<input type="checkbox"/> Operating Permit Inspection (PI)	<input type="checkbox"/> Initial Permit Inspection (IPI)	<input checked="" type="checkbox"/> Complaint Inspection (CI)
<input type="checkbox"/> Routine/Partial (RTPT)	<input type="checkbox"/> Follow-Up Inspection (Ref. Date: _____)	<input type="checkbox"/> Sample Collection (SC)
<input type="checkbox"/> Minor Source(s) Inspection (RFD)	<input type="checkbox"/> Stack Test Observation	<input type="checkbox"/> Multi-Media Inspection (MM)
<input type="checkbox"/> Other:	<input type="checkbox"/> Announced	

Annual Compliance Certification Received: <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	Date Received:
AIMS Report Received: <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	Date Received:

**Mark (X) All Activities That Apply:**

<input type="checkbox"/> File Review	<input checked="" type="checkbox"/> Pre-Inspection Briefing	<input checked="" type="checkbox"/> Exit Interview/Briefing
<input checked="" type="checkbox"/> Pre-Inspection Observations	<input type="checkbox"/> Check For New/Unreported Sources	<input type="checkbox"/> Sample(s) Collected
<input type="checkbox"/> Visible Emissions Observations	<input type="checkbox"/> Verify Operation of CEMS	<input type="checkbox"/> Other

**Comments/Recommendations:** Enforcement since last FCE  Yes  No (If yes, attach summary)

I arrived on site at 9:55 AM to conduct a complaint inspection. Winds were NNE at 1 mph and it was 44°F and cloudy. I met with Amber and Brent Pressley who stated that they scrape a small amount of hair off of some of the animal carcasses after the majority of hair has been removed in the scalding tank, and this only takes place 1-2 times a week sometime between 7 AM-5:30 PM when USDA inspectors are on site. I plan to come out to observe this process when it is occurring. ~~After~~ We then walked to the back of the property and I observed that all the rendering bins were empty. Ms. Pressley stated that MOPAC is still down

Compliance Status: <input checked="" type="checkbox"/> In <input type="checkbox"/> Out <input type="checkbox"/> Pending <input type="checkbox"/> Awaiting Co. Report		Needs a Follow-Up Inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Company Representative: <b>Amber Pressley</b>	Title: <b>Plant manager</b>	Signature: 	Date: <b>3/27/24</b>
DEP Representative: <b>Jennifer Ramos-Buschmann</b>	Title: <b>AO Specialist</b>	Signature: 	Date/Time: <b>3/27/24 10:55 AM</b>

This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.



# INSPECTION REPORT

Continued

Commonwealth of Pennsylvania  
Department of Environmental Protection  
Air Quality Program

and not accepting rendering, so all of their rendering is placed in a large trailer and hauled off site at the end of every day. I observed rendering being dumped into the trailer with a backhoe during the inspection. I noted minor rendering odors in that area at that time and the odors were noted only in that area. I observed the former compost area and noted no composting taking place.

Company -- plant name: Kingdom Provisions      Initials of representative interviewed: AP      Date: 3/27/24

Page 2 of 2      Reviewed By \_\_\_\_\_

- White - Site       Yellow - District Office       Pink - Regional Office